

Sep 21 16, 08:49a



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6176 FAX: (505) 334-6170
[http://emrwd.state.nm.us/ocd/District III/District.htm](http://emrwd.state.nm.us/ocd/District%20III/District.htm)

OIL CONS. DIV DIST. 3
SEP 29 2016

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test SEPTEMBER 20, 2016 Operator RIDE ENERGY API #30-0 43-2092.3

Property Name SANITIZADO Well No. 5-15 Location: Unit 5 Section 5 Township 20N Range 24W

Well Status (Shut-In or Producing) Initial PSI: Tubing 35 Intermediate N/A Casing 35 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	7	35		
10 min	0		35		
15 min	0		35		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	✓
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

Producing well

By

Johnny Brager
Plummer
(Position)

Witness

E-mail address