



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-8178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

OCT 19 2016

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10-19-16 Operator Chewton API #30-0 39-07081
Property Name Rincon Wet Well No. 78 Location: Unit 14 Township 27 Range 7
Well Status (Shut-In or Producing) Initial PSI: Tubing 82 Intermediate 476 Casing 91 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	476	91	139	91
10 min	0	476	91	38	91
15 min	0	476	91	8	91
20 min				2	92
25 min				1	92
30 min				1	92

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

Steady Flow		✓
Surges		
Down to Nothing		
Nothing	✓	
Gas		✓
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 4

REMARKS:

BH - Nothing when opened Int - hard to
med blow full 30 min test

By Lenny Moore
Crossfire
(Position)

Witness Mona Kuehling
Susan analysis - used bore schematic

E-mail address Lenny Moore 1979@gmail.com