

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

☒ Initial Report ☐ Final Report

Name of Company PRIDE ENERGY COMPANY	Contact TAYLOR PRIDE
Address PO BOX 701950, TULSA, OK 74170	Telephone No. 918-524-9200
Facility Name SAN ISIDRO #5-2	Facility Type PRODUCING

Surface Owner	Mineral Owner	Lease No. NMNM 56298
---------------	---------------	----------------------

**LOCATION OF RELEASE**

API# 30-043-20895

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	5	20 N	2 W	475	NORTH	1,750	EAST	SANDOVAL

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release OIL	Volume of Release 5 BBL.S.	Volume Recovered 11 YD <sup>3</sup>
Source of Release CONNECTION PIPE BETWEEN TANKS	Date and Hour of Occurrence 9/20/16 < UNKNOWN >	Date and Hour of Discovery 9/21/16 10:00 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

OIL CONS. DIV DIST. 3

Describe Cause of Problem and Remedial Action Taken.\*



OCT 12 2016

5 BBL.S. OF OIL SPILLED FROM PIPING BETWEEN 2 TANKS GETTING PLUGGED-OFF, RAN TANK OVER, ALL FLUIDS CONTAINED IN FIREWALL

Describe Area Affected and Cleanup Action Taken.\*

JOHNNY ARAGON (PUMPER) DISCOVERED SPILL AT 10:00 AM ON 9/21/16, AND CALLED ROUSTAOUT CREW AND VAC. TRUCK TO CLEAN UP THE SPILL AND REPAIR THE STOPPED-UP PIPING BETWEEN THE 2 TANKS

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: TAYLOR PRIDE	Approved by District Supervisor: Environmental Spec	
Title: PROJECT MANAGER	Approval Date: 10/26/16	Expiration Date:
E-mail Address: taylorp@pride-energy.com	Conditions of Approval: test For	Attached <input type="checkbox"/>
Date: 10/7/16	Phone: 918-524-9200	TDH (DRO - GRO - MRO), Bten

\* Attach Additional Sheets If Necessary

# 1005 16 300 300 24

①