



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3
NOV 1 2016

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 11-1-16 Operator BPAmerica API #30-0 45-27341
Property Name Rebu Middle Mesa SW Well No. 1 Location: Unit 32 Township 31 Range 7
Well Status (Shut-In or Producing) Initial PSI: Tubing 1437 Intermediate 18 Casing -10 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead			Int	Csg
	BH	Int	Csg		
TIME					
5 min	0	18	-10	9	-10
10 min	0	18	-10	9	-10
15 min	0	18	-10	0	-11
20 min				0	-10
25 min				0	-10
30 min				0	-10

FLOW CHARACTERISTICS

BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	✓
Nothing	
Gas	✓
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS: BH light blow through 1/4" needle valve to clead at 13 seconds.
light puff when opened after 5 min shut in. Int. Blow through
1/4" down to light blow at 2 min. pulled needle valve off and

By RTF
RTF
(Position)

Witness Mona Tuckling

E-mail address _____

clead at 14.5 min. - vapors.
Retest in 30 days - Gas analysis
Intermediate
Tuckling when opened
after 5 min shut