



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3
NOV 1 2016

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 11-1-16 Operator BP America API #30-0 4528553
Property Name KB Middle Mesa SW Well No. 2 Location: Unit M Section 11 Township 31 Range 7
Well Status (Shut-In or Producing) Initial PSI: Tubing 1228 Intermediate 22 Casing -10 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
5 min	0	22	-10	19	-10
10 min	0	22	-10	18	-10
15 min	0	22	-10	0	-10
20 min				0	-10
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	<u>✓</u> vapors
Surges	
Down to Nothing	<u>✓</u>
Nothing	
Gas	<u>✓</u>
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

BH. Light blow through 1/4" Valve to clear at 10 minutes
Light blow when opened after 5 min shut in - Int - Med blow
through 1/4" Valve Opened through 2" Valve at 10 minutes - Hard blow for
4 min.

By AKT

Witness

AKT, Fiscal LTR
(Position)

Gas analysis - Re test in 30 days

E-mail address _____