



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10-NOV-2016 Operator BP API #30-0 45 21790

Property Name FLORANCE GAS COM 5 Well No. 16A Location: Unit P Section 6 Township 30 Range 9

Well Status (Shut-In or Producing) Initial PSI: Tubing 120.8 Intermediate Casing 124 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>123.7</u>		
10 min	<u>0</u>		<u>123.8</u>		
15 min	<u>0</u>		<u>123.7</u>		
20 min	<u>0</u>		<u>123.8</u>		
25 min	<u>0</u>		<u>123.5</u>		
30 min	<u>0</u>		<u>123.6</u>		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	<u>X</u>
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

OIL CONS. DIV DIST. 3

NOV 10 2016

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS:

THE BRADEN HEAD WAS COMPLETELY DUG OUT FROM SURFACE.
THE BRADENHEAD WAS OPENED AND NOTHING CAME OUT.

By B. J. [Signature]

Witness John [Signature]
Ch [Signature] (Williams)

(Position)

E-mail address