

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric.htm

## BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test May 24, 2016 Operator Blocklicks GAS Resources API #30-039-25950	
Property Name Jicavilla 458-6 Well No. 4 Location: Unit E Section 6 Township 30N Range 3W	
Well Status(Shut-In or Producing) Initial PSI: Tubing 23 Intermediate M/A Casing 23 Bradenhead Ø	
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH	
PRESSURE Testing Bradenhead INTERM BH Int Csg Int Csg	FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE
TIME S NA 23	Steady Flow N/
10 min Ø ( 24 /4	Surges
15 min 8 26	Down to Nothing
20 min	Nothing
25 min	Gas
30 min	Gas & Water
Water	
If bradenhead flowed water, check all of the descriptions that apply below:  OIL CONS. DIV DIST.	
CLEAR FRESH SALTY	SULFURBLACK SEP 0 8 2016
5 MINUTE SHUT-IN PRESSURE BRADENHEAD 1 INTERMEDIATE 1/4	
REMARKS: Nothing on bradenhead when opened.	
By Kiet D. Vicenti Witness Witness	
(Position) E-mail address	