

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District ill/3distric.htm

## BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test May 27, 2016 Operator Blockhills Gas Resources API #30-0 39 - 26 104	
Property Name Jearilla 29-3-11 Well No. 1 Location: Unit P Section 11 Township 29N Range 3W	
Well Status(Shut-In or Producing) Initial PSI: Tubing @ Intermediate // Casing 6 Bradenhead @	
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH	
PRESSURE Testing Bradenhead INTERM BH Int Csg Int Csg	FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE
TIME 5 min 0 N/A 6 N/	Steady Flow
10 min 6 4	Surges
15 min 9 6	Down to Nothing
20 min	Nothing
25 min	Gas
30 min/	Gas & Water
WaterOIL CONS. DIV DIST.	
If bradenhead flowed water, check all of the descriptions that apply below:  SEP 0 8 2016	
CLEAR FRESH SALTY SULFUR BLACK	
5 MINUTE SHUT-IN PRESSURE BRADENHEAD Ø INTERMEDIATE	
REMARKS: nothing When broden head was opened.	
By Kier D. Vicenti Witness_	
By Kiet D. Vicenti Witness	
E-mail address	