

E-mail address

NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District iii/3distric.htm

CIL COMO, DAY DIST. 3

DEC 0 0 1013

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9-12-16 Operator	r: Enervest Operating, LLC API #30-039-06156
Property Name: <u>Jicarilla Cont. 146</u> Well No <u>. 02</u> Location: Unit: <u>J_Section: 4_Township: 25N_Range: 5W</u>	
Well Status(Shut-In or Producing) Initial PSI: Tubing \(\gamma \) Intermediate \(\subseteq \) Casing \(\subseteq \) Bradenhead \(\subseteq \)	
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH	
PRESSURE Testing Bradenhead INTERM BH Int Csg Int Csg	FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE
TIME 5 min 6 - 52	Steady Flow
10 min 6 - 52	Surges
15 min 0 - 52	Down to Nothing
20 min	Nothing
25 min	Gas
30 min	Gas & Water
Water	
If bradenhead flowed water, check all of the descriptions that apply below:	
CLEAR FRESH SALTY SULFUR BLACK	
5 MINUTE SHUT-IN PRESSURE BRADENHEAD O INTERMEDIATE	
REMARKS:	
DE TO COMIEST	
****FAILURE TO COMPLY *****FAILURE TO COMPLY ******FAILURE TO COMPLY ***********************************	
By Well 1	****FAILURE TO COMPLET *****FAILURE TO COMPLET ******FAILURE TO COMPLET ******FAILURE TO COMPLET ******FAILURE TO COMPLET ******FAILURE TO COMPLET ***********************************
Prod. Foreman	
(Position)	