

### BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 4/14/2016 Operator Encana API #30-0 39-22936  
Property Name Dunn Well No. 11 Location: Unit H Section 3 Township 23N Range 7W  
Pressure (Shut-In or Producing) Shut in Tubing 177 Intermediate n/a Casing 177 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:				BRADENHEAD	INTERMEDIATE
	BRADENHEAD	INTERMEDIATE	CASING		FLOWED	FLOWED
5 minutes	0		177	Steady Flow		
10 minutes	0		177	Surges		
15 minutes	0		177	Down to Nothing		
20 minutes				Nothing		
25 minutes				Gas		
30 minutes				Gas & Water		
				Water		

OIL CONS. DIV. DIST. 3  
NOV 14 2016

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE \_\_\_\_\_

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

By Michael Veazey Witness \_\_\_\_\_

Lease Operator

(Position)

\*\*\*\*FAILURE TO COMPLY  
WITH BRADENHEAD TEST  
MEMORANDUM DATED  
FEBRUARY 1, 2016