

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric.htm

DECCULLO

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 11-7-16 Operator: Enervest Operating, LLC API #30-039-20190	
Property Name: <u>Jic. Apache 102</u> Well No. <u>16</u> Location: Unit: <u>O</u> Section: <u>10</u> Township: <u>26N</u> Range: <u>4W</u>	
Well Status(Shut-In or Producing) Initial PSI: Tubing 6 Intermediate Casing 79 Bradenhead	
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH	
PRESSURE Testing Bradenhead INTERM BH Int Csg Int Csg	FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE
TIME 5 min 0 \ 79	Steady Flow
10 min 6 8 1	Surges
15 min 0 1 82	Down to Nothing
20 min	Nothing
25 min	Gas
30 min	Gas & Water
Water	
If bradenhead flowed water, check all of the descriptions that apply below:	
CLEAR FRESH SALTY	SULFURBLACK
5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE INTERMEDIATE INTERMEDIATE INTERMEDIATE INTERMEDIATE INTERMEDIATE	
REMARKS: SMINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE	
By Wille Jan W Prod, Foreman (Position)	itness
E-mail address	