

NEW MEXICO ENERGY, MONERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric.htm

OLCOND DA BOOK 3 DEC 0 9 2019

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9-14-16 Operato	r: Enervest Operating, LLC API #30-039-20210
Property Name: <u>Jicarilla Cont. 146</u> Well No <u>. 18</u> Location: Unit: <u>G</u> Section: <u>3</u> Township: <u>25N</u> Range: <u>5W</u>	
Well Status(Shut-In or Producing) Initial PSI: Tubing 30 Intermediate Casing 0 Bradenhead 2	
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH	
PRESSURE Testing Bradenhead INTERM BH Int Csg Int Csg	FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE
TIME 5 min 113	Steady Flow
10 min 0 16	Surges
15 min 0 1 8	Down to Nothing 💢
20 min	Nothing
25 min	Gas
30 min	Gas & Water
	Water
If bradenhead flowed water, check all of the descriptions that apply below:	
CLEAR FRESH SALTY SULFUR BLACK	
5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE	
REMARKS: Blew down in 5sec.	
By Wille	Witness***FAILURE TO COMPLY ****FAILURE TO COMPLY ***FAILURE TO COMPLY ***FAILURE TO COMPLY WITH BRADENHEAD TEST WITH BRANDUM DATED MEMORANDUM 1,2016 MEEBRUARY 1,2016
Proditoneman *** * FAILURENHE BATED	
(Position) **TH BRANDUI 1.2019 WITH BRANDUI 1.2019	
E-mail address	