



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3distric.htm](http://emnr.state.nm.us/ocd/District%20III/3distric.htm)

OIL CONS. DIV DIST. 3

DEC 09 2016

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9-19-16 Operator: Enervest Operating, LLC API #30-039-21511

Property Name: Huron Well No. 1A Location: Unit: E Section: 2 Township: 26N Range: 4W

Well Status(Shut-In or Producing) Initial PSI: Tubing 140 Intermediate — Casing 141 Bradenhead 7

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	1	142		
10 min	0	1	144		
15 min	0	1	147		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	X
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR — FRESH — SALTY — SULFUR — BLACK —

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE —

REMARKS:

Blew down in 3 sec.

By Willie J. Foreman
(Position)

Witness —

E-mail address —

*****FAILURE TO COMPLY
WITH BRADENHEAD TEST
MEMORANDUM DATED
FEBRUARY 1, 2016**