OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric.htm

DEC 0 9 2010

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9-15-16 Operator	r: Enervest Operating, LLC API #30-039-27780
Property Name: <u>Jicarilla B</u> Well No. 1B	Location: Unit: H Section: 26 Township: 26N Range: 4W
Well Status(Shut-In or Producing) Initial PSI: Tubing 19 Intermediate Casing 6 Bradenhead	
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH	
PRESSURE Testing Bradenhead INTERM BH Int Csg Int Csg	FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE
TIME 5 min 0 162	Steady Flow
10 min 0 165	Surges
15 min 0 167	Down to Nothing
20 min_	Nothing
25 min_	Gas
30 min	Gas & Water
	Water
If bradenhead flowed water, check all of the descriptions that apply below:	
CLEAR FRESH SALTY SULFURBLACK	
5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE REMARKS:	
	- LIGHT
By Wille Jel	witness***FAILURE TO COMPLY ****FAILURE TO COMPLY *****FAILURE TO COMPLY ****FAILURE TO COMPLY *****FAILURE TO COMPLY ******FAILURE TO COMPLY ******FAILURE TO COMPLY ******FAILURE TO COMPLY ******FAILURE TO COMPLY ***********************************
Prodi Foren an	****FAILUNENHERDATED
(Position)	WITH BORANDY 1, 20
E-mail address	FEBRU