



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL & GAS DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3distric.htm](http://emnr.state.nm.us/ocd/District%20III/3distric.htm)

OIL CONS. DIV DIST. 3

NOV 30 2016

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9-25-2016 Operator Western Minerals & Oil API # 30-039-06171

Property Name Jillison Well No. 1 Location: Unit 1 Section 1 Township 25N Range 2W

Well Status(Shut-In or Producing) Initial PSI: Tubing 76 Intermediate -- Casing 233 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		233		
10 min	0		233		
15 min	0		233		
20 min	0		233		
25 min	0		233		
30 min	0		233		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE _____

REMARKS:

_____ No Pressure _____

By Bob Chenault Witness Steven Gallegos

Pumper
(Position)

E-mail address Bob@ccinm.com

*****FAILURE TO COMPLY
WITH BRADENHEAD TEST
MEMORANDUM DATED
FEBRUARY 1, 2016**

✓