



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnrd.state.nm.us/ocd/District III/3distric.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-20-11 Operator Burlington API #30-0 39-07529
Property Name San Juan 29-7 Well No. 99 Location: Unit 29 Section 29 Township 29 Range 7
Well Status (Shut-In or Producing) Producing Initial PSI: Tubing 152 Intermediate 14 Casing 161 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing TIME	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
5 min	0	14	161	0	162
10 min				0	162
15 min				0	162
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

Steady Flow	
Surges	
Down to Nothing	/
Nothing	RCVD JUN 20 '11
Gas	/
Gas & Water	OIL CONS. DIV.
Water	DIST. 3

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS

Int. dead in 1 min 45 sec.
BH dead in 3 seconds.

By Juan C. Cordero

(Position)

Witness Monica Kuchling

E-mail address _____