



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

MAY 12 2016

Date of Test 4/13/16 Operator BP API #30-0 3927445

Property Name UEBU Well No. 499A Location: Unit J Section 20 Township 3N Range 6W

Well Status(Shut-In or Producing) Initial PSI: Tubing 7 Intermediate      Casing 1 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead			Int	Csg
	BH	Int	Csg		
TIME					
5 min	<u>0</u>		<u>1</u>		
10 min	<u>0</u>		<u>1</u>		
15 min	<u>0</u>		<u>1</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing <u>X</u>	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR      FRESH      SALTY      SULFUR      BLACK     

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE     

REMARKS:

Blew from 1" valve. BH had no flow.

By [Signature]

Witness     

(Position)

E-mail address