

## NEW MIEXICO ENERGY, MINIERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric.htm

DEC 0 9 2016

## **BRADENHEAD TEST REPORT**

(submit 1 copy to above address)

Date of Test Q - 2 7 - 1 Coperator: Enervest Operating, LLC API #30-039-82260		
Property Name: <u>Jicarilla B</u> Well No. 04 Location: Unit: <u>H_Section: 21 Township: 26N Range: 5W</u>		
Well Status(Shut-In or Producing) Initial PSI: Tubing 67 Intermediate Casing Bradenhead 2		
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH		
PRESSURE Testing Bradenhead INTI BH Int Csg Int	FLOW CHARACT ERM BRADENHEAD INT Csg	TERISTICS TERMEDIATE
TIME 5 min 6 80	Steady Flow	
10 min 0 83	Surges_	
15 min 0 85	Down to Nothing 🔍	
20 min	Nothing	
25 min_	Gas	
30 min_	Gas & Water	
Water		
If bradenhead flowed water, check all of the descriptions that apply below:		
CLEAR FRESH SALTY SULFUR BLACK		
5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE		
REMARKS:  Slew down in 1sec.		
		TO CAD TED _
	EAILURE EAILURE	ON 3016
By William De	Witness ******************************	ARY
By Witness **** FAILURE TO LOUIS (Position)  Witness **** FAILURE TO LOUIS WITNESS ***** FAILURE TO LOUIS WITNESS ****** FAILURE TO LOUIS WITNESS ***** FAILURE TO LOUIS WITNESS **** FAILURE TO LOUIS WITNESS ***** FAILURE		
E-mail address		