Form 3160-5 (February 2005)

(Instructions on page 2)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

RECEIVED

FEB 0 1 2017

OIL CONS. DIV DIST. 3

FORM APPROVE OMI TO 1004 01

Expires: March 31, 2007

5. Lease Serial No

SUNDRY NOTICES AND REPORTS ON WELLS				ffice N0-G-1403	N0-G-1403-1908	
Do not use this abandoned well	s form for propo I. Use Form 316	osals to drill or to 0-3 (APD) for suc	re-enter an Manag read of the proposals.	Mif Indian, A	Allottee or Tribe Name	
SUBMIT IN TRIPLICATE – Other instructions on page 2.				7. If Unit of CA/Agreement, Name and/or No. NMNM 135216A		
1. Type of Well				NIVINIVI 135	0210A	
M OH Well Con Well Out				The state of the s	8. Well Name and No.  W Lybrook Unit 743H	
Oil Well Gas Well Other  2. Name of Operator				9. API Well N		
WPX Energy Production, LLC				30-045-35729		
3a. Address       3b. Phone No. (incl.)         PO Box 640       Aztec, NM 87410       505-333-1808			e area code)	10. Field and Pool or Exploratory Area Lybrook Mancos W		
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) SHL: 1209' FSL & 1346' FWL, Sec 8, T23N, R8W BHL: 1496'FNL & 330' FEL, Sec 17 T23N, R8W				11. Country or Parish, State San Juan, NM		
12. CHECK	THE APPROPRIATE	BOX(ES) TO INDICAT	E NATURE OF NOTIC	E, REPORT OR O	THER DATA	
TYPE OF SUBMISSION			TYPE OF ACTION	N		
Notice of Intent	Acidize	Deepen	Production	(Start/Resume)	Water Shut-Off	
	Alter Casing	Fracture Treat	Reclamatio	n	Well Integrity	
Subsequent Report	Casing Repair	New Construction	n Recomplete	2	Other	
	Change Plans	Plug and Abando	n Temporaril	y Abandon	Intermediate Casing	
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disp	osal		
requirements, including red 1/25/17 - MIRU- note: 9-5/8" s	surface previously set @	9 339' by MoTe on 12/7/	16			
Psi Test W/ Antelope Services:S					ms, Kill Valves, Relief side Casing, Blind Rams, Kill Valves,	
Relief side Valves, Stinger flex h 1/26/17-1/27/17-Drilling ahead	ose, All outer Valves in	Choke Manifold, all test			cusing, bind nams, kin varves,	
1/28/17- TD 8-3/4" intermedia						
1/29/17-Run 137 jts 7", 23#, J-5						
Cement 7"Casing with 70% exce Wash @ 8.5# {20 Bbls}, follow						
followed by Tail Cement @ 13.5	5# { 116 BBLS/500 sks \	/ARICEM * class C} Displ	ace W/ Fresh H2o Totali	ng 226 Bbls Land Pl	lug 2,620 PSI & Bump up to	
3,175 PSI & Hold 5 min Floats H	leld got 1/2 Bbl Back o	n Bleed off85 bbls good o	ement back to surface.P	Plug Down 01/29/2	917 07:27 { BLM-Rep Rick	
Romaro Oncita ac Witness 1						
Romero Onsite as Witness } Psi Test 7" casing @ 1,500 psi f	or 30 min, Tested Good	d Recorded on CanRig EL	OR 🖊	EADAIN	ETON FIDING OFFICE	
Psi Test 7" casing @ 1,500 psi f 14. I hereby certify that the forego		d Recorded on CanRig EL	OR V	FARMIN BY:	CTON FILE OFFICE	
Psi Test 7" casing @ 1,500 psi f			itle Permit Tech III	BY:	CTON FILE SOFFICE	
Psi Test 7" casing @ 1,500 psi f  14. I hereby certify that the forego Name (Printed/Typed) Lacey Granillo	oing is true and correct.	10	itle Permit Tech III	BY:	CTON FILE OFFICE	
Psi Test 7" casing @ 1,500 psi f 14. I hereby certify that the forego Name (Printed/Typed)	Ser Roccia	10	ate2/1/17	BY:	CTON FILE COPPICE	
Psi Test 7" casing @ 1,500 psi f  14. I hereby certify that the forego Name (Printed/Typed) Lacey Granillo	Ser Roccia	Graniuo o	ate2/1/17	BY:	CTON FILE OFFICE	
Psi Test 7" casing @ 1,500 psi f  14. I hereby certify that the forego Name (Printed/Typed)  Lacey Granillo	Ser Roccia	Graniuo o	ate2/1/17	EARMIN BY:	Date	