



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONS. DIV DIST. 3

MAR 16 2017

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 3-16-17 Operator Burlington Res API #30-0 39-20385

Property Name San Juan 28 Well No. 107 Location: Unit M Section 23 Township 28 Range 6

Well Status (Shut-In or Producing) Initial PSI: Tubing 154 Intermediate 0 Casing 159 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing TIME	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
5 min	0	0	160	0	168
10 min	0	0	162	0	169
15 min	0	0	163	0	170
20 min	0	0	164		
25 min	0	0	165		
30 min	0	0	166		

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

Steady Flow	☒	☒
Surges	☐	☐
Down to Nothing	☐	☐
Nothing	☐	☒
Gas	☒	☐
Gas & Water	☐	☐
Water	☐	☐

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

Light flow when opened - nothing when
opened after 5 min shut in - nothing when opened
swsb bgt - gap w/liner nothing when opened after
5 min shut in

By Raymundo Brister

Witness

Monica Kuehling
Retired in 6 months w/c

(Position)

E-mail address _____