



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-APRIL-2017 Operator LOGOS API #30-0 45-28236

Property Name SEYMOUR Well No. 723 Location: Unit B Section 25 Township 31 Range 9

Well Status(Shut-In or Producing) Initial PSI: Tubing 5 Intermediate Casing 0 Bradenhead 12

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead	Csg	Int	Csg
TIME					
5 min	0	N/A	0		
10 min	0	1	0		
15 min	0		0		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	X	
Nothing		
Gas	X	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS: OPENED THE BRADENHEAD AND IT BLEW DOWN TO
0 IN 10 SECONDS

By

Witness John R. Dutton

(Position)

E-mail address

OIL CONS. DIV DIST. 3

APR 06 2017