



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

OIL CONNS. DIV DIST. 3

APR 05 2017

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-5-17 Operator Burlington Res API #30-0 45-33274
Property Name Bunt Mesa Well No. 2M Location: Unit 26 Section 26 Township 32 Range 7
Well Status (Shut-In or Producing) Initial PSI: Tubing 153 Intermediate 8 Casing 155 Bradenhead 2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	8	155	0	157
10 min	0	8	156	0	157
15 min	0	7	156	0	157
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	/
Nothing	
Gas	/
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS: BH Dead at 2 seconds - Nothing when opened
after 5 min shut in - Int Med Blow for 1 min 20 seconds
Down to Clear at 2 min 50 seconds - Nothing when
opened after 5 min shut in
By [Signature] Witness Monica Cuatrecasas
(Position)

E-mail address _____