

## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric.htm

## BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4/20/2017 Operator	Synergy API #30-043-21020
Property Name Synergy 21-7-7 Well No. 130 Location: Unit Section 7 Township 21 Range 7	
Well Status (Shut-In or Producing) Initial PSI: Tubing NA Intermediate NA Casing D Bradenhead D	
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH	
PRESSURE Testing Bradenhead INTERM BH Int Csg Int Csg	FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE
TIME 5 min 0 60)	Steady Flow
10 min D b01	Surges
15 min D 601	Down to Nothing
20 min D 601	Nothing
25 min 0 601	Gas
30 min 0 1 60K	Gas & Water
	Water
If bradenhead flowed water, check all of the descriptions that apply below:	
CLEAR FRESH SALTY SULFUR BLACK	
5 MINUTE SHUT-IN PRESSURE BRADENHEAD O INTERMEDIATE NA	
No pressure on BH, son during MIT	
1 tomas of the ad	
By her willing Witness watth bely	
(Position)	
E-mail address	