



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4/20/2017 Operator Synergy API #30-0 43-21032

Property Name Synergy 21-7-8 Well No. 132 Location: Unit D Section 8 Township 21 Range 7

Well Status (Shut-In or Producing) Initial PSI: Tubing NA Intermediate NA Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
5 min	0	S	631		
10 min	0		631		
15 min	0		631		
20 min	0		631		
25 min	0		631		
30 min	0		631		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	X	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE NA

REMARKS:

BA test conducted during MIT, no pressure on BH

By Shane Thomas Mullins

Witness

Janet D. Kelly

(Position)

E-mail address _____