



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnrd.state.nm.us/oed/District/III/3distric.htm>

OIL CONS. DIV DIST. 3

APR 26 2017

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-26-2017 Operator Southland Royalty API #30-045-32617

Property Name Hart Canyon 26 Well No. 15 Location: Unit E Section 26 Township 31 Range 10

Well Status (~~Shut In~~ or Producing) Initial PSI: Tubing 0 Intermediate NA Casing 2 Bradenhead 93.4

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	NA	2.0		
10 min	0		2.0		
15 min	0		2.0		
20 min	0		1.6		
25 min	0		2.0		
30 min	0		2.2		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow	X	
Surges		
Down to Nothing		
Nothing		
Gas	X	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 3.8 psi INTERMEDIATE NA

REMARKS: Well had high pressure on BH when tested last. Got gas sample, waiting on results.

Hard blow to steady flow in 20 seconds. Light steady flow after first five minutes. Light steady flow at 10 minutes - casing drop to 0 psi. Light steady flow for remainder of test.

By Jeff Graham
Pumper
(Position)

Witness Thomas H. H. NMOLD

E-mail address jgraham@ctfieldsvcs.com