



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/district.htm](http://emnr.state.nm.us/ocd/District%20III/district.htm)

OIL CONS. DIV DIST. 3
MAY 02 2017

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-2-17 Operator Domunion API #30-0 31-20102
Property Name Santa Fe Well No. 17 Location: Unit 7 Section 7 Township 17 Range 8
Well Status (Shut-In or Producing) Initial PSI: Tubing 18 Intermediate N/A Casing 70 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>90</u>		
10 min	<u>0</u>		<u>90</u>		
15 min	<u>0</u>		<u>90</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>/</u>
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE N/A

REMARKS:

Med light blow to dead at 3 seconds - long
When opened after 5 min shut in
Gas well?

By

James R. Lopez

(Position)

Witness

Monica Tuckling

E-mail address _____