



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
[http://emrdr.state.nm.us/ocd/District III/3ddistrict.htm](http://emrdr.state.nm.us/ocd/District%20III/3ddistrict.htm)

OIL CONS. DIV DIST. 3

MAY 09 2017

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-9-2017 Operator Dommon API #30-0 31-20413
Property Name Santa Fe Railroad Well No. 87 Location: Unit 2 Section 1 Township 17 Range 9
Well Status (Shut-In or Producing) Initial PSI: Tubing 0 Intermediate 1/1 Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead			Int	Csg
	BH	Int	Csg		
TIME					
5 min	<u>0</u>		<u>0</u>		
10 min	<u>0</u>		<u>0</u>		
15 min	<u>0</u>		<u>0</u>		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	<u>1/1</u>	
Nothing		
Gas	<u>1/1</u>	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 1/1

REMARKS:

Light blow to dead at 5 seconds - light
blow to dead at 4⁴⁰ seconds when opened after
5 min shut-in

By Ralph Gamella Jr.
Field Supervisor
(Position)

Witness Monica Kuchling

E-mail address _____