



(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/oed/District III/3distric.htm](http://emnrd.state.nm.us/oed/District%20III/3distric.htm)

OIL CONS. DIV DIST. 3
MAY 02 2017

(submit 1 copy to above address)

Date of Test 5-2-17 Operator Donumon API #30-0 31-20451
Property Name Santa Fe Railroad Well No. 40 Location: Unit Section 7 Township 17 Range 8
Well Status (Shut-In or Producing) Initial PSI: Tubing NA Intermediate NA Casing open Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		open		
10 min	0		"		
15 min					
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR_____ FRESH_____ SALTY_____ SULFUR_____ BLACK_____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE

REMARKS:

REMARKS: Nothing when opened - Casing open
Nothing when opened after 5 min shut in

By Kempwood 12/10/02

Witness Monica Ruckelshaus

(Position)

E-mail address _____