



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

MAY 04 2017

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-4-17 Operator Domunion API #30-0 31-20608
Property Name HSU Well No. 95 Location: Unit B Section 1 Township 17 Range 9
Well Status (Shut-In or Producing) Initial PSI: Tubing N/A Intermediate N/A Casing open Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM		
	BH	Int	Csg	Int	Csg	
TIME						
5 min	<u>0</u>		<u>Open</u>			
10 min	<u>0</u>		<u>"</u>			
15 min	<u>0</u>		<u>"</u>			
20 min						
25 min						
30 min						

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	<u>/</u>
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS: Casing open - Nothing when opened - Nothing when opened after 5 min shut-in

By Ramiro Lopez

Witness Moments

(Position)

E-mail address _____