



OIL COMPANY DIST. 3

MAY 02 2017

**OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410**

(505) 334-6178 FAX: (505) 334-6170

[http://emnrd.state.nm.us/ocd/District III/3ddistrict.htm](http://emnrd.state.nm.us/ocd/District%20III/3ddistrict.htm)

(submit 1 copy to above address)

Date of Test 5-2-17 Operator Domunion API #30-0 31-20836
Property Name Santa Fe Trail Road Well No. 47 Location: Unit 1 Section 7 Township 17 Range 8
Well Status (Shut-In or Producing) Initial PSI: Tubing NA Intermediate NA Casing open Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		open		
10 min	0		"		
15 min	0		"		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0.

INTERMEDIATE

REMARKS:

REMARKS: Nothing when opened. Nothing when
opened after 5 min shut in

By Larjensund/10/2000

Witness Donna Lucking

(Position)

E-mail address