



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnrud.state.nm.us/ocd/District/III3district.htm>

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

MAY 17 2017

(submit 1 copy to above address)

Date of Test 5/17/2017 Operator Burlington API #30-039-06876

Property Name San Juan 27-5 Unit Well No. 17 Location: Unit Section 29 Township 27 Range 5

Well Status (Shut-In or Producing) Initial PSI: Tubing NA Intermediate 90 Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	90	0	TSTM	610
10 min	0	90	0	TSTM	610
15 min	0	90	0	TSTM	610
20 min				TSTM	608
25 min				TSTM	608
30 min				TSTM	608

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	X
Gas	X
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

BH through 2", Int through 2" ran during MFT, Int blew down to breath in 45 sec
vapor @ 5 min

By VICTOR A. MONTORA

Witness

[Signature]

WELL SITE SUPERVISOR

(Position)

E-mail address