



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III3district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9-MAY-2017 Operator LOPEZ O/BULLINGTON API #30-0 39-20106

Property Name SAN JUAN 28-S Well No. 77 Location: Unit 6 Section 27 Township 28 Range 5

Well Status(Shut-In or Producing) Initial PSI: Tubing _____ Intermediate 8 Casing 599 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>8</u>	<u>599</u>	<u>0</u>	<u>590</u>
10 min	<u>0</u>	<u>8</u>	<u>590</u>	<u>0</u>	<u>590</u>
15 min	<u>0</u>	<u>8</u>	<u>590</u>	<u>0</u>	<u>590</u>
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>X</u>
Nothing	<u>X</u>
Gas	<u>X</u>
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD _____ INTERMEDIATE _____

REMARKS:

OPENED THE BRADENHEAD AND NOTHING CAME OUT.
OPENED THE INTERMEDIATE AND IT BLEW DOWN TO
NOTHING IN 3 MINUTES

By V. A. Montoya VICTOR A. MONTOKA
Witness _____

WEBSITE SUPERVISOR
(Position)

E-mail address _____

OIL CONS. DIV DIST. 3
MAY 09 2017