



NEW MEXICO ENERGY, MINERALS  
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NM 87410  
(505 334-6178 FAX: (505) 334-6170  
<http://www.emnrd.state.nm.us/ocd/>

OIL CONS. DIV DIST. 3  
MAY 10 2017

**BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Date of Test 4-20-17 Operator Thompson API # 20-039-20936  
 Property Name VEAN #11 Location: Unit 4 Section 3 Township 23N Range 17E  
 (Well Name and Number)  
 Pressure (Shut-in or Producing) Tubing 71 Intermediate \_\_\_\_\_ Casing 82 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Flow Description	Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor			
5 minutes	<u>0</u>	<u>82</u>				Steady Flow		
10 minutes	<u>0</u>	<u>82</u>				Surges		
15 minutes	<u>0</u>	<u>82</u>				Down to Nothing		
20 minutes						No Flow	<u>X</u>	
25 minutes						Gas		
30 minutes						Gas and Water		
5 minute SI	<u>0</u>	<u>82</u>				Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear \_\_\_\_\_ Fresh \_\_\_\_\_ Salty \_\_\_\_\_ Sulfur \_\_\_\_\_ Black \_\_\_\_\_

5 Minute Shut-in Bradenhead 0 Intermediate \_\_\_\_\_

REMARKS:

\_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

By Mike Wagner  
Lease Operator  
 (Position)

Witness \_\_\_\_\_