



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6176 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/district.htm](http://emnrd.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 24-MAY-2017 Operator DUGAS API #30-0 45-21127

Property Name STATE COM Well No. 1 Location: Unit A Section 16 Township 32 Range 12

Well Status (Shut-In or Producing) Initial PSI: Tubing 30 Intermediate N/A Casing 253 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>N/A</u>	<u>252</u>		
10 min	<u>0</u>	<u>S</u>	<u>253</u>		
15 min	<u>0</u>	<u>S</u>	<u>253</u>		
20 min				<u>N/A</u>	
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	<u>X</u>	<u>N/A</u>
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE _____

REMARKS: OPENED THE BRADEN HEAD AND NOTHING CAME OUT.

By Brian W. [Signature]

Witness John [Signature]

(Position)

E-mail address _____

OIL CONS. DIV DIST. 3
MAY 24 2017

3 BAT'S USED ON OIL