



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/district.htm](http://emnrd.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 2-MAY-2017 Operator SOUTHLAND API #30-0 45-28648

Property Name VANDERWART A Well No. 12 Location: Unit 6 Section 11 Township 29 Range 8

Well Status(Shut-In or Producing) Initial PSI: Tubing 10 Intermediate NA Casing 2 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					
	BH	Bradenhead	INTERM	Int	Csg	
TIME						
5 min	0	N/A	2			
10 min	0	1	2			
15 min	0	1	2			
20 min						
25 min						
30 min						

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	X	
Nothing		
Gas	X	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE NA

REMARKS:

OPENED THE BRADENHEAD AND IT BLEW DOWN IN
2 SECONDS

By Coely Hannah

Witness John D. Dumas

Lease Operator

(Position)

E-mail address channah@ctfieldsucs.com

OIL CONS. DIV DIST. 3

MAY 02 2017

OIL CONS. DIV