



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

MAY 15 2017

Date of Test 5-15-2017 Operator Southland Royalty API #30-0 45-3415

Property Name Navajo Lake Well No. 102 Location: Unit I Section 10 Township 32 Range 6

Well Status (~~Shut-In~~ or Producing) Initial PSI: Tubing 71 Intermediate NA Casing 109 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead		INTERM	
		Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>NA</u>	<u>109</u>		
10 min	<u>0</u>	<u>2</u>	<u>109</u>		
15 min	<u>0</u>	<u>3</u>	<u>109</u>		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	<u>X</u>	
Nothing		
Gas	<u>X</u>	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE BRADENHEAD Ops INTERMEDIATE NA

REMARKS:

Light puff to nothing in less than one second on BH when opened
Nothing on BH after five minute shut in.

By Jonathan Hardy
Lease Operator
(Position)

Witness John H. H. NMCD

E-mail address _____