



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

MAY 30 2017

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-30-17 Operator Logos Op. LLC API #30-0 43-21165

Property Name J. Carulla Well No. 3E Location: Unit 0 Section 10 Township 22 Range 3

Well Status (Shut-In or Producing) Initial PSI: Tubing 43 Intermediate N/A Casing 59 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>60</u>		
10 min	<u>0</u>		<u>60</u>		
15 min	<u>0</u>		<u>60</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>/</u>
Nothing	
Gas	<u>/</u>
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

Light blow to dead at 10 seconds - nothing
when opened after 5 min shut in

By Eugene Burbank
Lead
(Position)

Witness Monica Kuehling

E-mail address _____