



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distrct.htm](http://emnrd.state.nm.us/ocd/District%20III/3distrct.htm)

OIL CONS. DIV DIST. 3

JUN 01 2017

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-1-17 Operator Burlington Gas API #30-0 45-29998
Property Name Helmsted Well No. 1B Location: Unit 22 Township 30 Range 10
Well Status (Shut-In or Producing) Initial PSI: Tubing 78 Intermediate 478 Casing 81 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	479	82	21	83
10 min	0	480	82	11	84
15 min	0	480	82	12	84
20 min				15	84
25 min				17	84
30 min				21	85

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		✓
Surges		
Down to Nothing		
Nothing	✓	
Gas		
Gas & Water		✓
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 124

REMARKS:

Nothing when opened - Nothing when opened after
5 min shut-in. Int fluid blow - Nothing at 6 min 17 lbs.
• 6 = 21 gallons in 5 min. Surged at 30 minutes lot more water when

By Mitchell Senan

Witness Melissa Kuehling

MSO
(Position)

E-mail address _____