



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

[http://emrdr.state.nm.us/ocd/District III/3distric.htm](http://emrdr.state.nm.us/ocd/District%20III/3distric.htm)

OIL CONS. DIV DIST. 3

JUN 01 2017

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-1-17 Operator Concepcion API #30-0 45-34105

Property Name Guge Well No. 3F Location: Unit E Section 20 Township 30 Range 10

Well Status(Shut-In or Producing) Initial PSI: Tubing 80 Intermediate 6 Casing 166 Bradenhead 1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0	6	166	0	166
10 min	0	6	166	0	166
15 min	0	6	166	0	166
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	☒	☒
Nothing		
Gas	☒	☒
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

BH - light blow to dead at 2 seconds when opened
Nothing when opened after 5 min shut in
Int med blow to dead at 55 seconds. Nothing when opened
By MITCHELL SEVEN MS
(Position)

Witness

Monica Kuehling after min shut in

E-mail address _____