



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

JUN 06 2017

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-6-17 Operator Dommon API #30-0 31-08 05185

Property Name Hsu Well No. 2 Location: Unit L Section 1 Township 17 Range 9

Well Status (Shut-In or Producing) Initial PSI: Tubing    Intermediate    Casing    Bradenhead   

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM		
	BH	Bradenhead Int	Csg	Int	Csg	
TIME						
5 min						
10 min						
15 min						
20 min						
25 min						
30 min						

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR    FRESH    SALTY    SULFUR    BLACK   

5 MINUTE SHUT-IN PRESSURE BRADENHEAD    INTERMEDIATE   

REMARKS:

dug 6 feet no bradenhead

By [Signature]

(Position)

Witness [Signature]

E-mail address