



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONS. DIV. DIST. 3

JUN 16 2017

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 6-16-17 Operator Waggoner API # 30-0 4533865

Property Name Hazle SWD Well # 1 Location: Unit C Sec 30 Twp 7N Rge 10

Land Type:

State /
Federal /
Private /
Indian /

Well Type:

Water Injection /
Salt Water Disposal /
Gas Injection /
Producing Oil/Gas /
Pressure observation /

Temporarily Abandoned Well (Y/N): / TA Expires: /

Casing Pres. 0
Bradenhead Pres. 0
Tubing Pres. 1000
Int. Casing Pres. N/A

Thg. SI Pres. /
Tbg. Inj. Pres. /

Max. Inj. Pres. /

Pressured annulus up to 430 psi. for 30 mins. Test passed/failed

REMARKS:


Fracker Set 6620
TD 10965 by perf 6684 - Bottom 6710
dropped to 425 last 10 minutes

By Jason Hest
(Operator Representative)

Witness Monica Kuehling
(NMOCD)

(Position)

Revised 02-11-02



OIL CONSERVATION DIST. 3
JUN 16 2017

GRAPHIC CONTROLS CORPORATION
BUFFALO, NEW YORK

CHART NO. MC MP-1000

METER

CHART PUT ON

TAKEN OFF

LOCATION

REMARKS

Traverse St. 1
C-30-2410
Dugan Prod.

Spec. He as
Monica Kuehling
NMOC
Passed
6-16-17

PRINTED IN U.S.A.