

RECEIVED

Form 3160-5
(June 2015)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No. 1004-0137
Expires: January 31, 2018

JUN 07 2017

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

Farmington Field Office
Bureau of Land Management

5. Lease Serial No.
NMNM109399
6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on page 2

7. If Unit of CA/Agreement, Name and/or No.

1. Type of Well
 Oil Well Gas Well Other

8. Well Name and No.
Chaco 2308 061 #397H

2. Name of Operator
WPX Energy Production, LLC

9. API Well No.
30-045-35639

3a. Address
PO Box 640 Aztec, NM 87410

3b. Phone No. (include area code)
505-333-1816

10. Field and Pool or Exploratory Area
Nageezi Gallup (330')

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
SHL: 2100' FSL & 325' FEL SEC 6, T23N, R8W
BHL: 2414' FSL & 458' FWL SEC 6, T23N, R8W

11. Country or Parish, State
San Juan NM

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Hydraulic Fracturing	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	<input checked="" type="checkbox"/> Flared/Gas
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	<input checked="" type="checkbox"/> Sample

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplate horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be perfonned or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has detennined that the site is ready for final inspection.)

WPX flared during the W Lybrook 703H/704H/711H/713H/743H/744H & W Lybrook 701H/702H Frac.
Attached is a gas sample.

ACCEPTED FOR RECORD OIL CONS. DIV DIST. 3

JUN 09 2017

JUN 13 2017

FARMINGTON FIELD OFFICE
BY: *[Signature]*

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)
Lacey Granillo

Title Permit Tech III

Signature

[Signature]

Date 6/7/17

THE SPACE FOR FEDERAL OR STATE OFICE USE

Approved by _____ Title _____ Date _____

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C Section 1001 and Title 43 U.S.C Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



2030 Afton Place
 Farmington, NM 87401
 (505) 325-6622

Analysis No: WP170092
 Cust No: 85500-12590

Well/Lease Information

Customer Name:	WPX ENERGY PRODUCTION, LLC	Source:	SEPARATOR METER
Well Name:	CHACO 2308-06H #397H; SEP MTR	Pressure:	88 PSIG
County/State:	SAN JUAN NM	Sample Temp:	81 DEG. F
Location:		Well Flowing:	
Field:		Date Sampled:	06/01/2017
Formation:		Sampled By:	CODY M.
Cust. Stn. No.:	62307960	Foreman/Engr.:	CODY BOYD

Remarks: RAN ON 06/05/2017

Analysis

Component::	Mole%:	**GPM:	*BTU:	*SP Gravity:
Nitrogen	5.093	0.5630	0.00	0.0493
CO2	0.519	0.0890	0.00	0.0079
Methane	67.899	11.5600	685.78	0.3761
Ethane	10.530	2.8280	186.35	0.1093
Propane	9.672	2.6760	243.36	0.1473
Iso-Butane	1.344	0.4420	43.71	0.0270
N-Butane	3.240	1.0260	105.70	0.0650
I-Pentane	0.555	0.2040	22.20	0.0138
N-Pentane	0.545	0.1980	21.85	0.0136
Hexane Plus	0.603	0.2700	31.78	0.0200
Total	100.000	19.8560	1340.73	0.8292

* @ 14.730 PSIA DRY & UNCORRECTED FOR COMPRESSIBILITY

**@ 14.730 PSIA & 60 DEG. F.

COMPRESSIBILITY FACTOR (1/Z): 1.0045
 BTU/CU.FT (DRY) CORRECTED FOR (1/Z): 1349.8
 BTU/CU.FT (WET) CORRECTED FOR (1/Z): 1326.3
 REAL SPECIFIC GRAVITY: 0.8325

GPM, BTU, and SPG calculations as shown above are based on current GPA factors.

DRY BTU @ 14.650: 1342.5
 DRY BTU @ 14.696: 1346.7
 DRY BTU @ 14.730: 1349.8
 DRY BTU @ 15.025: 1376.8

CYLINDER #: CHACO #1
 CYLINDER PRESSURE: 90 PSIG
 DATE RUN: 6/1/17 12:00 AM
 ANALYSIS RUN BY: SHYANN ELLEDGE