



**NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT**

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

23228

Date of Test 5-10-17 Operator THOMPSON API # 30-039-23228
 Property Name NAGUEZI 3#1 Location: Unit C Section 3 Township 23N Range 7W
 (Well Name and Number)
 Pressure (Shut-in or Producing) Tubing 100 Intermediate _____ Casing 133 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	0	133					
10 minutes	0	133					
15 minutes	0	133					
20 minutes							
25 minutes							
30 minutes							
5 minute SI	0	133					

Steady Flow		
Surges		
Down to Nothing		
No Flow	X	
Gas		
Gas and Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

OIL CONS. DIV DIST. 3

JUN 05 2017

5 Minute Shut-in Bradenhead 0 Intermediate _____

REMARKS:

By Mike Wagner
Lease Operator
 (Position)

Witness _____