

OIL CONS. DIV DIST. 3

JUN 19 2017

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-19-17 Operator Zindongfakes API #30-0 45-07974

Property Name Satana Well No. 2 Location: Unit Section 21 Township 29 Range 11

Well Status(Shut-In or Producing) Initial PSI: Tubing 117 Intermediate ✓1A Casing 153 Bradenhead 2.8

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME	0		153		
5 min	0		153		
10 min	0		153		
15 min	0		153		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD INTERMEDIATE	
Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD

INTERMEDIATE VA

REMARKS:

REMARKS: Puff when opened - Nothing when
opened after 5 min shut in

House lap

By Matthew Tiedt

Witness [Signature]

(Position)

E-mail address _____