



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

OIL CONS. DIV DIST. 3

JUN 19 2017

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-19-17 Operator Burlington Res API #30-0 45-24673

Property Name Mangum Well No. 1E Location: Unit 29 Section 29 Township 29 Range 11

Well Status (Shut-In or Producing) Initial PSI: Tubing 142 Intermediate 141 Casing 141 Bradenhead 11

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					
	Bradenhead			INTERM		
	BH	Int	Csg	Int	Csg	
TIME						
5 min	0		141			
10 min	0		142			
15 min	0		142			
20 min						
25 min						
30 min						

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	✓
Nothing	
Gas	
Gas & Water	✓
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD

0

INTERMEDIATE

141

REMARKS:

Ardenhead sign - water appeared - surged to
Nothing in 25 seconds. 141 when opened after
5 min shut in

By Shirley Smith

Witness Mona Kuchling

(Position)

E-mail address _____