



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://emnrd.state.nm.us/ocd/District III3district.htm>

**BRADENHEAD TEST REPORT**

(submit 1 copy to above address)

Date of Test 5-30-17 Operator: Enervest Operating, LLC API # 30-039-21581

Property Name: Jic. Apache 102 Well No. 29 Location: Unit: G Section: 9 Township: 26N Range: 4W

Well Status(Shut-In or Producing) Initial PSI: Tubing 15 Intermediate      Casing 20 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
5 min	0		120		
10 min	0		122		
15 min	0		122		
20 min	0		123		
25 min	0		124		
30 min	0		124		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	✓	
Gas		
Gas & Water		
Water		

OIL CONS. DIV DIST. 3  
JUN 09 2017

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR      FRESH      SALTY      SULFUR      BLACK     

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE     

REMARKS: valve malfunction can't open Braden head. replaced valve  
no blow nor pressure

By Orrin Sandaul Witness     

Operator  
(Position)

E-mail address