

OIL CONS. DIV DIST. 3

JUN 26 2017

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://emnr.state.nm.us/ocd/DistrictIII/3distic.htm>

**BRADENHEAD TEST REPORT**

(Submit 1 copies to above address)

Date of Test May 12, 2017 Operator DJ Simmons API #30-0 45-23217  
 Property Name Simmons S Well No. 1A Location: Unit P Section 25 Township 29N Range 09W  
 Pressure (Shut-In or Producing) Producing Tubing 21 Intermediate NA Casing 38 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURES:

TESTING TIME	BRADENHEAD			INTERMEDIATE		Steady Flow	Surges	Down to Nothing	Nothing	Gas	Gas & Water	Water	BRADENHEAD	INTERMEDIATE
	BH	INT	CSG	INT	CSG								FLOWED	FLOWED
5 minutes	0		38											
10 minutes	0		38											
15 minutes	0		38					X						
20 minutes														
25 minutes														
30 minutes														

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_  
 5 MINUTE SHUT-IN \_\_\_\_\_ BRADENHEAD 0 INTERMEDIATE \_\_\_\_\_

REMARKS:  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

BH had a puff and blew down to nothing

By Tylynn Birdsley Witness \_\_\_\_\_  
 \_\_\_\_\_  
 Lease Operator \_\_\_\_\_  
 \_\_\_\_\_  
 (Position)