NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric.htm

OIL CONS. DIV DIST. 3

JUL 1 2 2017

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-12-14 Operator Burlington Res API #30-0 39-07852

Property Name San Juan 30-6 Unit Well No. 45 Location: Unit ___ Section 15 Township 30 Range 6

Well Status(Shut-In or Producing) Initial PSI: Tubing 115 Intermediate 0 Casing 115 Bradenhead 3

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead BH	Bradenhead Int	Bradenhead Csg	INTERM Int	INTERM Csg
TIME 5 min	0	0	116	0	116
10 min	0	0	116	0	117
15 min	0	0	116	0	117
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	✓	
Nothing		✓
Gas	✓	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR_____ FRESH_____ SALTY_____ SULFUR_____ BLACK_____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS: BH blew to dead in 20 seconds - long puff when opened after 5 min shut in. Int nothing when opened. Nothing when opened after 5 min shut in

By [signature] Witness Monica Kuehling

MSO
(Position)

E-mail address _____