



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/district.htm](http://emnr.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-11-17 Operator Encana Oil & Gas API #30-0 43-21129
Property Name Lybrook Well No. 014 Location: Unit I Section 32 Township 23N Range 6W
Well Status (Shut-In or Producing) Initial PSI: Tubing 51 Intermediate N/A Casing 88 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

11:30

PRESSURE

Testing	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>N/A</u>	<u>88</u>		
10 min	<u>0</u>	<u>N/A</u>	<u>89</u>		
15 min	<u>0</u>	<u>N/A</u>	<u>88</u>	<u>N/A</u>	
20 min	<u>0</u>	<u>N/A</u>	<u>89</u>	<u>N/A</u>	
25 min	<u>0</u>	<u>N/A</u>	<u>89</u>		
30 min	<u>0</u>	<u>N/A</u>	<u>89</u>		

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

Steady Flow

Surges

Down to Nothing

Nothing X

Gas

Gas & Water

Water

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

Plunger Running - Left BH shut

By

Arthur Sullivan

Witness

(Position)

Lead Tech

OIL CONS. DIV DIST. 3

JUL 14 2017

E-mail address: arthur.sullivan@encana.com