



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III3district.htm](http://emnrd.state.nm.us/ocd/District%20III3district.htm)

02

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 2-2-12 Operator Encana Oil & Gas API #30-0 43-21146
Property Name Lybrook Well No. M31-02H Location: Unit M Section 31 Township 23N Range 6W
Well Status(Shut-In or Producing) Initial PSI: Tubing 47 Intermediate N/A Casing 93 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing TIME	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
5 min	<u>0</u>	<u>N-A</u>	<u>95</u>		
10 min	<u>0</u>	<u>1</u>	<u>95</u>	<u>N/A</u>	
15 min	<u>0</u>		<u>93</u>	<u>N/A</u>	
20 min	<u>0</u>		<u>94</u>	<u>N/A</u>	
25 min	<u>0</u>		<u>93</u>	<u>N/A</u>	
30 min	<u>0</u>	<u>N-A</u>	<u>95</u>		

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N-A

REMARKS:

Plunger running - Left Shut-Bradenhead 95

By

Arthur Sullivan
Lead Tech
(Position)

Witness

OIL CONS. DIV DIST. 3

JUL 10 2017

E-mail address arthur.sullivan@encana.com